

# MVME2502

## Quick Start Guide

P/N:6806800S32B (February 2014)

### 1 What's in the box?

Make sure you receive all items of your shipment:

- MVME2502 VMEbus board
- Other items that were ordered
- Printed *Safety Notes*



When installing or servicing the module or accessories, strictly observe the safety precautions in the *Safety Notes*. Otherwise, personal injury or property damage may occur.

### 2 Observe ESD-safe measures

- Use either a properly grounded ESD wrist strap or make sure that you are working in an ESD safe environment.
- Connect to the ESD connector at the front or the rear of the system.

### 3 Prepare the installation site

- For information on the environmental and power requirements, see the *MVME2502 Installation and Use* manual.
- Operating temperatures refer to the temperature of the air circulating around the blade and not to the actual component temperature.

### 4 Install the RTM

1. Power down all equipment and disconnect the power cable from the AC power source.
2. Remove the chassis cover.
3. Remove the filter panel(s) from the card slot(s) at the rear of the chassis (if the chassis has a rear card cage).
4. Install the top and bottom edge of the transition module into the rear guides of the chassis.
5. Ensure that the levers of the two injector/ejectors are in the outward position.
6. Slide the transition module into the chassis until resistance is felt.
7. Move the injector/ejector levers in an inward direction.
8. Verify that the transition module is properly seated and secure it to the chassis using the two screws adjacent to the injector/ejector levers.
9. Connect the cables to the transition module.



## 5 Install the PMC/XMC Support

1. Remove the PMC/XMC filler plate from the front panel cut-out.
2. Slide the front bezel of the PMC/XMC into the cut-out from behind. The front bezel of the PMC/XMC module will be flushed with the board when the connectors on the module align with the mating connectors on the board.
3. Align the mating connectors properly and apply minimal pressure to the PMC/XMC until it is seated to the board.
4. Insert the four PMC/XMC mounting screws through the mounting holes on the bottom side of the board, and then thread the four mount points on the PMC/XMC. Tighten the screws.
5. Install the board into the appropriate card slot. Make sure that the board is well seated into the backplane connectors. Do not damage or bend connector pins.
6. Replace the chassis or system cover.
7. Reconnect the system to the power source and then turn on the system.

## 6 Install the board

The MVME2502 does not support hot swap. Power off the slot or the system and make sure that the serial ports and switches are properly configured.

1. Attach an ESD strap to your wrist. Attach the other end of the strap to an electrical ground. Make sure that it is securely fastened throughout the procedure.
2. Remove VME filler panels from the VME enclosures, as appropriate.
3. Install the top and bottom edge of the board into the guides of the chassis.
4. Ensure that the levers of the two injector/ejectors are in the outward position.
5. Slide the board into the chassis until there is resistance.
6. Simultaneously move the injector/ejector levers in an inward direction.
7. Verify that the board is properly seated and secure it to the chassis using the two screws located adjacent to the injector/ejector levers.
8. Connect the appropriate cables to the board.
9. To remove the board from the chassis, reverse the procedure and press the red locking tabs (IEEE handles only) to extract the board.

### Finding more information

For more information on the product, see the *MVME2502 Installation and Use* and other related documentation.

Visit our Web site

<http://www.artesyn.com/computing>. Use SUPPORT>TECHNICAL DOCUMENTATION link to look for technical documentation.

### Technical Assistance

To request technical assistance, visit our Web site <http://www.artesyn.com>.